

Product Change Notice

Product Model Name: D120 – D480
Date: November 2004
Reference ECO No: 16669

Reason for Change

This PCN announces the release of D-Series library firmware version 1.18. This firmware is available at no cost from Plasmon via the website www.plasmontech.com.

Description of Change

The following changes/features are incorporated into the new firmware release:

- Modified lift motor limit encoder from 1000 to 5000 in position_lift() to resolve recurrent 61h errors.

Firmware

To confirm the current firmware version using the front panel display menus, select Setup Library > Firmware Version.

If the new firmware is installed the front panel displays: **XXXSlot/XXDrive Firmware V1.18** in bold text, where the Xs are number identifiers.

The following table shows the release history of the D-Series firmware.

Code	Release Date	ECO#
1.17	September 2003	15710
1.18	November 2004	16669

Contact Information for Technical Questions:

Americas and Asia Pacific

Plasmon Technical Support Team
United States Calls: 1-877-585-6793
International Calls: 1-719-593-4437
Fax: 1-719-593-4192
Email: tech.support@plasmon.com
Internet: www.plasmon.com

Europe, Africa, and Middle East

Plasmon Technical Support Team
United States Calls: +44 (0) 1763 262 963
Fax: +44 (0) 1763 264 407
Email: support@plasmon.co.uk
Internet: www.plasmon.co.uk