



Product Change Notice

Product Model Name: Sony F561
Date: April 2008
Reference ECO No: ECAMO2008001

Reason for Change

Sony has released firmware version 1.14 to resolve the following issues on the F561 9.1 GB Magneto Optical Drive.

Description of Change

- Modified the calibration range for read power.
- Improves interoperability with MCC (Mitsubishi Chemical Company) media.

Firmware

Code	Release Date	ECO#
1.14	October 2008	ECAMO2008002
1.13	April 2008	ECAMO2008001
1.12	January 2004	ECAMO2006001E
1.11	March 2004	16187

Contact Information for Technical Questions:

Americas and Asia Pacific

Plasmon Technical Support Team
United States Calls: 1-877-585-6793
International Calls: 1-719-593-4437
Fax: 1-719-593-4192
Email: tech.support@plasmon.com
Internet: www.plasmon.com

Europe, Africa, and Middle East

Plasmon Technical Support Team
International Calls: +44 (0) 1763 262 963
Fax: +44 (0) 1763 264 407
Email: support@plasmon.co.uk
Internet: www.plasmon.com