

# Product Change Notice

**Product Model Name: D875 – D2175**  
**Date: February 2007**  
**Reference ECO No: 18337**

## Reason for Change

This PCN announces the release of Enterprise D-Series library firmware version 4.00. This firmware is available at no cost from Plasmon via the website [www.plasmontech.com](http://www.plasmontech.com).

## Description of Change

The following changes/features are incorporated into the new firmware release:

- Resolved intermittent internal stack overflow on the main controller circuit board that could cause the library to lock up.

## Firmware

To confirm the current firmware version using the front panel display menus, select Setup Library > Firmware Version. If the new firmware is installed the front panel displays: **XXXSlot/XXDrive Firmware V4.00** in bold text, where the Xs are number identifiers.

The following table shows the release history of the Enterprise D-Series firmware.

| Code | Release Date  | ECO#  |
|------|---------------|-------|
| 3.01 | March 2003    | 15550 |
| 3.02 | March 2003    | 15579 |
| 3.03 | August 2005   | 17099 |
| 3.04 | Not Posted    | 17419 |
| 3.05 | May 2006      | 17689 |
| 4.00 | February 2007 | 18337 |

### Contact Information for Technical Questions:

#### Americas and Asia Pacific

Plasmon Technical Support Team  
United States Calls: 1-877-585-6793  
International Calls: 1-719-593-4437  
Fax: 1-719-593-4192  
Email: [tech.support@plasmon.com](mailto:tech.support@plasmon.com)  
Internet: [www.plasmon.com](http://www.plasmon.com)

#### Europe, Africa, and Middle East

Plasmon Technical Support Team  
International Calls: +44 (0) 1763 262 963  
Fax: +44 (0) 1763 264 407  
Email: [support@plasmon.co.uk](mailto:support@plasmon.co.uk)  
Internet: [www.plasmon.com](http://www.plasmon.com)